

State of Ohio Environmental Protection Agency

Southwest District Office

401 East Fifth Street Dayton, Ohio 45402-2911 (513) 285-6357 FAX (513) 285-6249 LOG A-0313

Nov 24 8 28 AM '99

FILE: 6446.6

-- 2631

George V. Voinovich Governor

November 22, 1999

Mr. Johnny Reising U.S. Department of Energy, Fernald Area Office P.O. Box 538705 Cincinnati, OH 45253-8705

RE: COMMENTS - PSP FOR A1PII CERTIFIED FOR REUSE AREAS, TRAP RANGE, SECTOR 2C, AND SECTOR 3 CERTIFICATION SAMPLING

Dear Mr. Reising:

Ohio EPA has reviewed DOE's November 1, 1999 submittal on the "Project Specific Plan for Area 1, Phase II Certified for Reuse Areas, Trap Range, Sector 2C, and Sector 3 Certification Sampling". Ohio EPA approves the sampling of all Certification Units, with the exception of A1P2-S3HR-04, A1P2-S3SA-02 and A1P2-S2SA-09. Attached are Ohio EPA's comments on the document.

If you have any questions, please contact Donna Bohannon, Michelle Waller or me.

Sincerely,

Thomas A. Schneider

Fernald Project Manager

Office of Federal Facilities Oversight

CC:

Jim Saric, U.S. EPA

Terry Hagen, FDF Ruth Vandergrift, ODH

Mark Shupe, HSI GeoTrans

Francie Hodge, Tetra Tech EM Inc.

Q:\femp\ou5\A1P2\certpsp.WPD

Ohio EPA Comments on the PSP for A1PII Certified for Reuse Areas, Trap Range, Sector 2C and Sector 3 Certification Sampling

1.) Commenting Organization: OEPA

Commentor: OFFO

Section #: 2.1

Pg. #: 2-3 Line #: 2-6

Code: C

Original Comment #:

Comment: A.) How will the top 6 inches of native soil be determined?

- B.) OEPA does not feel that one sample from each CU that was part of Removal Action 14 is enough. More samples need to be added to ensure all contamination was removed during RA 14. Also, please include a map showing the locations of RA 14 overlaid on the current CUs and sampling locations.
- C.) Has any characterization been done on the fill which was 'from an unknown source'?
- D.) This section needs to state that if contamination is found at depth, the soil will be dug up and resampled.

2.) Commenting Organization: OEPA

Commentor: OFFO

Section #: Figure 2-3

Pg. #: Line #:

Code: C

Original Comment #:

Comment: The CU east of S2-NI-03 and S2-NI-04 is not labeled. Please correct.

3.) Commenting Organization: OEPA

PA Commentor: OFFO

Section #: 2.3.2

Pg. #: 2-6 Line #: 28-32

Code: C

Original Comment #:

Comment: As discussed in a phone call on November 8, 1999 with FDF personnel, OEPA feels that all suite designators for the samples should be designated before the sample collection. In doing so, the possibility of errors being made by the sampling crew can be eliminated. Please revise the document to include designators for all samples in the PSP.

Data Quality Objectives

4.) Commenting Organization: OEPA

Commentor: OFFO

Section #: 7.0

Pg. #: 9 of 12

Line #:

Code: C

Original Comment #:

Comment: The paragraph labeled Physical Samples specifies areas in A2P3 which are not within the scope of this project. Please correct.